SDMS US EPA Region V

Imagery Insert Form

Document ID:

| 165585 |
|--------|
|--------|

Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:

| IncludesX COLOR or RESOLUTION variations. Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible thimages. The original document is available for viewing at the Superfund Records Center. Specify Type of Document(s) / Comments: URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED Document is available at the EPA Region 5 Records Center. | ment page(s) is more legible than the Center. GRADIENT CONTOUR MAP rials with such information are not ava |
|--|--|
| IncludesX COLOR or RESOLUTION variations. Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible the images. The original document is available for viewing at the Superfund Records Center. Specify Type of Document(s) / Comments: URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX _ or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | GRADIENT CONTOUR MAP |
| Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible the images. The original document is available for viewing at the Superfund Records Center. Specify Type of Document(s) / Comments: URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | GRADIENT CONTOUR MAP |
| Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible the images. The original document is available for viewing at the Superfund Records Center. Specify Type of Document(s) / Comments: URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: Oversized X or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | GRADIENT CONTOUR MAP |
| Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible the images. The original document is available for viewing at the Superfund Records Center. Specify Type of Document(s) / Comments: URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | GRADIENT CONTOUR MAP |
| Specify Type of Document(s) / Comments: URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are n in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX or Format. Due to certain scanning_equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | GRADIENT CONTOUR MAP |
| URS REVISIONS FOLD OUT MAPS; PARTIALLY SCANNED MAGNETIC GRADIENT CONTOUR MAP Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are n in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX_ or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | rials with such information are not av |
| Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are n in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | rials with such information are not a |
| This document contains highly sensitive information. Due to confidentiality, materials with such information are not in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments: Unscannable Material: OversizedX or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | |
| Unscannable Material: OversizedX or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | |
| Oversized X or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | |
| Oversized X or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | |
| Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The ori document is available for viewing at the Superfund Records center. Specify Type of Document(s) / Comments: MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | |
| MAGNETIC GRADIENT CONTOUR MAP w/ GEOPHYSICAL SURVEY GRID - PARTIALLY SCANNED | not available in SDMS. The origina |
| | ·s: |
| | D - PARTIALLY SCANNED |
| Document is available at the EPA Region 5 Records Center. | |
| | |
| Specify Type of Document(s) / Comments: | |

Rev. 07/10/02

Sauget Area 2 Sites Group

February 1st, 2002

Mr. Mike Ribordy U.S. EPA - Region 5 77 West Jackson Boulevard (SR-6J) Chicago, Illinois 60604-3590

RE: Sauget Area 2 Sites

Deliver by Overnight Mail Monday Delivery

Dear Mike:

Attached, please find a Memorandum summarizing the sampling investigation recently completed at Site Q.

Also included is a CD ROM that contains the following information:

In Excel Format:

The original data received from STL laboratories.

In Acrobat / PDF Format:

Dot maps summarizing the results of the Site Q sampling for:

Total VOCs in Soil Gas

Total VOCs in Soil

Total SVOCs in Soil

Total Antimony in Soil

Total Arsenic in Soil

Total Barium in Soil

Total Cadmium in Soil

Total Chromium in Soil

Total Copper in Soil

Total Lead in Soil

Total Mercury in Soil

Total Nickel in Soil

Total Selenium in Soil

Total Silver in Soil

Total Thallium in Soil

Total Zinc in Soil

A Magnetic Gradient Contour Map of Site Q

Site Q map showing sampling locations

Maps of Sites O, P, Q, R and S showing the proposed locations of the Test Trenches

With your package we have also included a paper copy of all of the above, with the exception of the original data. Paper copies of the original data will be sent to you with the January SA2SG Monthly Report.

Any questions please call.

Sincerely,

Steven D. Smith Project Coordinator

cc: Sandra Bron - Illinois EPA
Kevin de la Bruere - U.S. Fish & Wildlife
Mike Henry - Illinois Department of Natural Resources
Peter Barrett - CH2M Hill
SA2SG File

URS

Memorandum

Date:

January 4, 2002

To:

Steve Smith, SA2SG Project Manager

From:

Bob Veenstra, URS Project Manager

Subject:

Sauget Area 2 - Summary of Site Q Screening Activities

A field investigation was conducted at Site Q during the period beginning on October 30, 2001 and continuing through November 29, 2001. During this time, both soil and soil gas samples were collected for analysis in on-site laboratories and a magnetometer survey was done at the site.

As discussed in the work plan, the magnetometer survey at this site was to be done on a 50-foot grid, resulting in magnetometer readings being collected every 50 feet throughout the site. The magnetometer survey crew actually collected readings every 2.5 feet along transects that ran across the site at fifty-foot intervals. There were numerous obstacles encountered on site, since commercial operations are active on much of Site Q. Several obstacles (such as buildings and piles of mulch, gravel, sand, etc.) could not be moved and therefore no magnetometer survey was done in these areas. Where obstacles were present on site that could be moved (such as pallets or truck trailers), they were temporarily relocated when necessary to obtain a magnetometer reading at a minimum of every fifty feet along each transect. (Note that the USEPA's subcontractor (CH2M Hill) approved moving magnetometer locations as much as 20 feet to avoid obstacles, and this was done when necessary.) The magnetometer survey was completed across the entire site, except for the areas of the site where we did not have access agreements. The results of this magnetometer survey are presented on Figure 1.

In addition to significant obstacles being present due to commercial operations, tree and brush removal was also necessary in the southern portion of Site Q in order to complete both the Geoprobe sampling and the magnetometer survey.

As discussed in the work plan, both soil and soil gas samples were collected across the entire site on a 200-foot grid. This 200-foot grid was independent of the magnetometer survey's 50-foot grid (i.e. they were not necessarily co-located – mostly due to access issues). Based on the configuration of the Site Q boundaries and this 200-foot grid, a total of 228 potential sampling locations were identified. There were 190 Geoprobe locations at Site Q that were located on property for which access agreements were in place during this field investigation. Of these 190 Geoprobe locations, two locations (Q-142 and Q-203) were moved to a part of the site for which access agreements were not in place, to avoid underground pipelines. All Geoprobe sample locations are presented on Figure 2. Table 1 presents all of the Geoprobe sample locations and identifies if they were completed during this investigation.

USEPA's subcontractor (CH2M Hill) approved moving Geoprobe locations as much as 30 feet without additional approval from them, to avoid obstacles on site. An agreement was also reached that any



Geoprobe location that needed to be moved greater than 30 feet and less than 100 feet should be cleared with them prior to sampling that location. Additionally it was agreed that any location that needed to be moved greater than 100 feet would not be done, with their approval. Clarification logs were filled out when any Geoprobe sample was moved greater than 30 feet, since USEPA's approval was necessary for all of these locations.

Four of the 190 Geoprobe locations for which access agreements were in place will not be done as agreed to by the USEPA's subcontractor, for the following reasons:

- Q-29 will not be done because it is located underneath a building and we cannot get within 100 feet of the original location.
- Q-87 will not be done because refusal was encountered at two feet below ground surface at several locations in this area, after moving the boring in several different directions.
- Q-104 will not be done because it is located in an area that has very recently been backfilled with soil and concrete rubble with rebar. It does not appear to be safe to drive on this area with a truck.
- Q-126 will not be done because it is located in the center of a pile of concrete rubble and debris, and we cannot get within 100 feet of the original location.

As a result, 184 Geoprobe locations were completed during this field investigation. Both soil and soil gas samples were collected from all of these locations except for two (as approved by the USEPA's subcontractor), for the following reasons:

- No soil gas sample was collected from sample location Q-212 because groundwater was encountered in the boring at a very shallow depth.
- No soil gas sample was collected from sample location Q-221 because groundwater was encountered in the boring at a very shallow depth.

Four soil gas "step-out" locations were identified and implemented, in accordance with the work plan, to the south of the southern boundary of Site Q. These samples were numbered: Q-229, Q-230, Q-231 and Q-232. The first location Q-229 was "stepped out" approximately 100 feet from the southern site boundary, and the remaining locations were located approximately 200 feet, 300 feet and 400 feet from the southern site boundary, respectively.

All of the 182 soil gas samples that were collected were analyzed on site by Hydrologic, Inc, for total volatile organic compounds. These results were reported in parts per billion volume (ppbV) and are presented on Figure 3.

All of the 184 soil samples that were collected were analyzed on site by Severn Trent Laboratories for volatile organic compounds, semi-volatile organic compounds and metals by XRF. These results are presented on Figures 4 through 18.

URS

Prior to beginning Geoprobe sampling at this site, six hand auger samples were collected from across the site for metals analysis only. These samples were to be run in triplicate at the local Severn Trent Laboratory that was located in Earth City, Missouri. These metals sample results were used by the on-site Severn Trent Laboratory as a part of an XRF calibration study for this site.


| I | Soil Gas 9 | Samples | Soil Sa | mples | |
|----------|------------|-----------|------------|-----------|---|
| Sample | Was sample | | Was sample | Date | |
| Location | collected? | Collected | collected? | Collected | Comments |
| Q-1 | Yes | 11/6/01 | Yes | 11/6/01 | |
| Q-2 | Yes | 11/6/01 | Yes | 11/6/01 | |
| Q-3 | Yes | 11/7/01 | Yes | 11/6/01 | |
| Q-4 | Yes | 11/13/01 | Yes | 11/6/01 | |
| Q-5 | Yes | 11/7/01 | Yes | 11/6/01 | |
| Q-6 | Yes | 11/7/01 | Yes | 11/6/01 | |
| Q-7 | Yes | 11/7/01 | Yes | 11/6/01 | |
| Q-8 | Yes | 11/7/01 | Yes | 11/6/01 | |
| Q-9 | Yes | 11/7/01 | Yes | 11/7/01 | ATT |
| Q-10 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-11 | Yes | 11/7/01 | Yes | 11/7/01 | |
| Q-12 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-13 | Yes | 11/7/01 | Yes | 11/7/01 | |
| Q-14 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-15 | Yes | 11/7/01 | Yes | 11/7/01 | |
| Q-16 | Yes | 11/18/01 | Yes | 11/14/01 | <u></u> |
| Q-17 | Yes | 11/7/01 | Yes | 11/7/01 | ABA1-44B-47-10/2017-1 |
| Q-18 | Yes | 11/18/01 | Yes | 11/14/01 | } |
| Q-19 | Yes | 11/18/01 | Yes | 11/14/01 | |
| Q-20 | Yes | 11/19/01 | Yes | 11/14/01 | |
| Q-21 | Yes | 11/18/01 | Yes | 11/14/01 | |
| Q-22 | Yes | 11/18/01 | Yes | 11/14/01 | |
| Q-23 | Yes | 11/18/01 | Yes | 11/18/01 | Moved 60 ft southeast due to debris and fallen trees |
| Q-24 | Yes | 11/19/01 | Yes | 11/8/01 | Wild for the control of the fact that the fact the control of the fact that the fact the control of the fact that |
| Q-25 | Yes | 11/19/01 | Yes | 11/8/01 | <u></u> |
| Q-26 | Yes | 11/19/01 | Yes | 11/8/01 | ************************************** |
| Q-27 | Yes | 11/19/01 | Yes | 11/8/01 | ************************************** |
| Q-28 | Yes | 11/19/01 | Yes | 11/8/01 | \$5555555555555555555555555555555555555 |
| Q-29 | No | NA | No | NA | Will not be collected-under building |
| Q-30 | Yes | 11/19/01 | Yes | 11/8/01 | THE TOTAL STREET STREET |
| Q-31 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-32 | Yes | 11/18/01 | Yes | 11/14/01 | MARIE - DAY |
| Q-33 | Yes | 11/19/01 | Yes | 11/8/01 | , |
| Q-34 | Yes | 11/19/01 | Yes | 11/8/01 | |
| Q-35 | Yes | 11/19/01 | Yes | 11/8/01 | |
| Q-36 | Yes | 11/11/01 | Yes | 11/8/01 | |
| Q-37 | Yes | 11/11/01 | Yes | 11/8/01 | |
| Q-38 | Yes | 11/11/01 | Yes | 11/8/01 | |
| Q-39 | Yes | 11/19/01 | Yes | 11/8/01 | |
| Q-40 | Yes | 11/11/01 | Yes | 11/11/01 | |
| Q-41 | Yes | 11/19/01 | Yes | 11/8/01 | 4 |
| Q-42 | Yes | 11/20/01 | Yes | 11/8/01 | |
| Q-43 | Yes | 11/20/01 | Yes | 11/8/01 | <u></u> |
| Q-44 | Yes | 11/7/01 | Yes | 11/7/01 | |
| Q-45 | Yes | 11/10/01 | Yes | 11/10/01 | |
| Q-46 | Yes | 11/11/01 | Yes | 11/11/01 | |
| Q-47 | Yes | 11/19/01 | Yes | 11/15/01 | |
| Q-48 | Yes | 11/20/01 | Yes | 11/15/01 | *************************************** |
| Q-49 | Yes | 11/20/01 | Yes | 11/15/01 | |


| | Soil Gas S | Samples | Soil Sa | mples | |
|----------|------------|-----------|------------|-----------|--|
| Sample | Was sample | | Was sample | | |
| Location | collected? | Collected | collected? | Collected | Comments |
| Q-50 | Yes | 11/11/01 | Yes | 11/9/01 | |
| Q-51 | Yes | 11/10/01 | Yes | 11/10/01 | |
| Q-52 | Yes | 11/11/01 | Yes | 11/11/01 | |
| Q-53 | Yes | 11/19/01 | Yes | 11/15/01 | |
| Q-54 | Yes | 11/20/01 | Yes | 11/15/01 | |
| Q-55 | Yes | 11/20/01 | Yes | 11/15/01 | |
| Q-56 | Yes | 11/11/01 | Yes | 11/7/01 | |
| Q-57 | Yes | 11/10/01 | Yes | 11/10/01 | |
| Q-58 | Yes | 11/11/01 | Yes | 11/11/01 | |
| Q-59 | Yes | 11/19/01 | Yes | 11/15/01 | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |
| Q-60 | Yes | 11/20/01 | Yes | 11/15/01 | |
| Q-61 | Yes | 11/11/01 | Yes | 11/7/01 | <u> </u> |
| Q-62 | Yes | 11/11/01 | Yes | 11/9/01 | |
| Q-63 | Yes | 11/10/01 | Yes | 11/10/01 | ~ |
| Q-64 | Yes | 11/11/01 | Yes | 11/11/01 | |
| Q-65 | Yes | 11/19/01 | Yes | 11/15/01 | |
| Q-66 | Yes | 11/20/01 | Yes | 11/15/01 | Moved 39 ft northwest due to coal pile |
| Q-67 | Yes | 11/9/01 | Yes | 11/8/01 | |
| Q-68 | Yes | 11/11/01 | Yes | 11/8/01 | |
| Q-69 | Yes | 11/10/01 | Yes | 11/10/01 | Moved 41 ft southeast due to gravel pile |
| Q-70 | Yes | 11/11/01 | Yes | 11/11/01 | |
| Q-71 | Yes | 11/19/01 | Yes | 11/15/01 | ************************************** |
| Q-72 | Yes | 11/20/01 | Yes | 11/15/01 | |
| Q-73 | Yes | 11/9/01 | Yes | 11/8/01 | |
| Q-74 | Yes | 11/18/01 | Yes | 11/8/01 | |
| Q-75 | Yes | 11/10/01 | Yes | 11/10/01 | |
| Q-76 | Yes | 11/18/01 | Yes | 11/18/01 | ************************************** |
| Q-77 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-78 | Yes | 11/18/01 | Yes | 11/15/01 | |
| Q-79 | Yes | 11/9/01 | Yes | 11/9/01 | |
| Q-80 | Yes | 11/9/01 | Yes | 11/9/01 | |
| Q-81 | Yes | 11/10/01 | Yes | 11/10/01 | |
| Q-82 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-83 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-84 | Yes | 11/18/01 | Yes | 11/15/01 | |
| Q-85 | Yes | 11/9/01 | Yes | 11/9/01 | |
| Q-86 | Yes | 11/9/01 | Yes | 11/9/01 | |
| Q-87 | No | NA | No | NA | Will not be collected - refusal at 2 ft below ground surface |
| Q-88 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-89 | Yes | 11/16/01 | Yes | 11/16/01 | ************************************* |
| Q-90 | Yes | 11/18/01 | Yes | 11/15/01 | *************************************** |
| Q-91 | Yes | 11/9/01 | Yes | 11/9/01 | |
| Q-92 | Yes | 11/9/01 | Yes | 11/9/01 | |
| Q-93 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-94 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-95 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-96 | Yes | 11/18/01 | Yes | 11/15/01 | |
| Q-97 | Yes | 11/18/01 | Yes | 11/9/01 | |
| Q-98 | Yes | 11/18/01 | Yes | 11/9/01 | |


| | Soil Gas Samples | | Soil Samples | | |
|----------|------------------|-----------|--------------|-----------|---|
| Sample | Was sample | | Was sample | Date | |
| Location | collected? | Collected | collected? | Collected | Comments |
| Q-99 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-100 | Yes | 11/18/01 | Yes | 11/18/01 | Moved 48 ft northwest due to concrete rubble piles |
| Q-101 | Yes | 11/18/01 | Yes | 11/18/01 | |
| Q-102 | Yes | 11/18/01 | Yes | 11/15/01 | |
| Q-103 | Yes | 11/18/01 | Yes | 11/15/01 | ###################################### |
| Q-104 | No | NA | No | NA | Will not be collected - in new fill area |
| Q-105 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-106 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-107 | Yes | 11/17/01 | Yes | 11/17/01 | ### ### ############################## |
| Q-108 | Yes | 11/16/01 | Yes | 11/16/01 | V, |
| Q-109 | Yes | 11/16/01 | Yes | 11/16/01 | , |
| Q-110 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-111 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-112 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-113 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-114 | Yes | 11/17/01 | Yes | 11/17/01 | ************************************** |
| Q-115 | Yes | 11/13/01 | Yes | 11/16/01 | |
| Q-116 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-117 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-118 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-119 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-120 | Yes | 11/17/01 | Yes | 11/17/01 | ************************************** |
| Q-121 | Yes | 11/17/01 | Yes | 11/17/01 | ************************************** |
| Q-122 | Yes | 11/17/01 | Yes | 11/17/01 | ************************************** |
| Q-123 | Yes | 11/16/01 | Yes | 11/16/01 | ************************************** |
| Q-124 | No | NA | No | ÑA | No access agreement in place, no sample collected |
| Q-125 | Yes | 11/17/01 | Yes | 11/17/01 | \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ |
| Q-126 | No | NA | No | NA | Will not be collected - under debris pile |
| Q-127 | Yes | 11/17/01 | Yes | 11/17/01 | Moved 53 ft northeast due to rubble pile |
| Q-128 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-129 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-130 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-131 | Yes | 11/16/01 | Yes | 11/16/01 | hamman |
| Q-132 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-133 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-134 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-135 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-136 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-137 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-138 | Yes | 11/16/01 | Yes | 11/16/01 | *************************************** |
| Q-139 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-140 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-141 | No | NA NA | No No | NA | No access agreement in place, no sample collected |
| Q-142 | No | NA | No | NA | Moved to railroad's property - no access agreement in |
| | | 4.4.4. | | | place, no sample collected |
| Q-143 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-144 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-145 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-146 | No | NA | No | NA | No access agreement in place, no sample collected |


| | Soil Gas S | Samples | Soil Samples | | |
|----------|------------|-----------|--------------|-----------|--|
| Sample | Was sample | | Was sample | Date | |
| Location | collected? | Collected | collected? | Collected | Comments |
| Q-147 | No | NΑ | No | NA | No access agreement in place, no sample collected |
| Q-148 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-149 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-150 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-151 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-152 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-153 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-154 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-155 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-156 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-157 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-158 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-159 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-160 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-161 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-162 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-163 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-164 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-165 | Yes | 11/15/01 | Yes | 11/15/01 | ************************************** |
| Q-166 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-167 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-168 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-169 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-170 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-171 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-172 | Yes | 11/16/01 | Yes | 11/16/01 | Moved 42 feet southeast due to underground pipelines |
| Q-173 | Yes | 11/17/01 | Yes | 11/17/01 | |
| Q-174 | Yes | 11/12/01 | Yes | 11/12/01 | |
| Q-175 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-176 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-177 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-178 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-179 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-180 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-181 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-182 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-183 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-184 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-185 | Yes | 11/12/01 | Yes | 11/12/01 | |
| Q-186 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-187 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-188 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-189 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-190 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-191 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-192 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-193 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-194 | Yes | 11/16/01 | Yes | 11/16/01 | |
| Q-195 | Yes | 11/13/01 | Yes | 11/13/01 | <u></u> |


| | Soil Gas S | Samples | Soil Samples | | |
|----------------|------------|----------------------|--------------|----------------------|--|
| Sample | Was sample | Date | Was sample | Date | |
| Location | collected? | Collected | collected? | Collected | Comments |
| Q-196 | Yes | 11/12/01 | Yes | 11/12/01 | |
| Q-197 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-198 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-199 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-200 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-201 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-202 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-203 | No | NA | No | NA | Moved to railroad's property - no access agreement in |
| | | | | | place, no sample collected |
| Q-204 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-205 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-206 | Yes | 11/12/01 | Yes | 11/12/01 | |
| Q-207 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-208 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-209 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-210 | No | NA | No | NA | No access agreement in place, no sample collected |
| Q-211 | Yes | 11/15/01 | Yes | 11/15/01 | Moved 44 ft southeast due to underground pipelines |
| Q-212 | No | NA | Yes | 11/15/01 | No soil gas due to shallow water in hole |
| Q-213 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-214 | Yes | 11/12/01 | Yes | 11/12/01 | |
| Q-215 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-216 | Yes | 11/13/01 | Yes | 11/13/01 | |
| Q-217 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-218 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-219 | Yes | 11/14/01 | Yes | 11/14/01 | |
| Q-220 | Yes | 11/12/01 | Yes | 11/12/01 | |
| Q-221 | No | NA 14/10/24 | Yes | 11/13/01 | No soil gas due to shallow water in hole |
| Q-222 | Yes | 11/13/01 | Yes | 11/13/01 | A |
| Q-223 | Yes | 11/15/01 | Yes | 11/15/01 | Moved 36 feet south due to sloped area with fallen trees |
| Q-224 Q-225 | Yes Yes | 11/12/01 11/12/01 | Yes Yes | 11/12/01 11/12/01 | |
| Q-225 Q-226 | Yes Yes | 11/12/01 | Yes Yes | 11/12/01 | |
| Q-227 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-228 | Yes | 11/15/01 | Yes | 11/15/01 | |
| Q-228 Q-229 | Yes | 11/19/01 | No | NA | Stepout point - for soil gas only |
| Q-230 | Yes | 11/19/01 | No No | NA NA | Stepout point - for soil gas only |
| Q-231 | Yes | 11/19/01 | No No | NA NA | Stepout point - for soil gas only |
| Q-232 | Yes | 11/19/01 | No | NA NA | Stepout point - for soil gas only |
| Q-1001 | No No | NA | Yes | 10/30/01 | Metals sample only for XRF Calibration Study |
| Q-1002 | No No | NA NA | Yes | 10/30/01 | Metals sample only for XRF Calibration Study |
| Q-1003 | No | NA NA | Yes | 10/30/01 | Metals sample only for XRF Calibration Study |
| Q-1004 | No | NA NA | Yes | 10/30/01 | Metals sample only for XRF Calibration Study |
| Q-1005 | No | NA NA | Yes | 10/30/01 | Metals sample only for XRF Calibration Study |
| Q-1006 | No | NA NA | Yes | 10/30/01 | Metals sample only for XRF Calibration Study |


















































0 300
SCALE FEET

LEGEND

Proposed Trench Locations
(Not to Scale)


SAUGET AREA 2 RI/FS SUPPORT SAMPLING PLAN SAUGET, ILLINOIS


AN PROJECT NO. 2320010024.02


URS

DRN. BY: djd 1/31/01 DSGN. BY: by CHKD. BY:

Site P Waste, Soil, and Leachate Sampling Locations FIG. NO. 5







Ø 300

SCALE

FEET

SAUGET AREA 2 RI/FS SUPPORT SAMPLING PLAN SAUGET, ILLINOIS 2

PROJECT NO. 2320010024.02

LEGEND

Proposed Trench Locations (Not to Scale)

URS

DRN. BY:djd 1/31/01 DSGN. BY:bv

CHKD. BY:

Site S Waste, Soil, and Leachate Sampling Locations FIG. NO.